



GEMPLUX TEST REPORT

Super Stainless

Abstract

Test carried out on Super Stainless – Stainless Steel Protector to evaluate if corrosion once removed by the product would come back

Mayelyn Blackerby
Quality Control Engineer
mayelyn@gemlux.com
www.gemlux.com

[800.874.4506](tel:800.874.4506) Tel
[904.269.5905](tel:904.269.5905) Fax
[904.444.1752](tel:904.444.1752) Cell
[140 Industrial Loop](http://www.gemlux.com)
[Orange Park, FL 32073](http://www.gemlux.com)

Viewing Salt Spray Sample: (# 832)

Hinge 3 x 2 Cutting
 Item #: Edge
 Source: G8234
 Date Created: 06/03/16
 Created By: Mayelyn Alvarez
 Start Test
 Time: 6/3/16 8:00
 Test Hours: 400
 Finish Result: **Pass**

Sample Comments:

| Date | Hours | User | Comment |
|----------|-------|-----------------|------------------------------------------------|
| 06/04/16 | 24 | Mayelyn Alvarez | No corrosion present |
| 06/07/16 | 100 | Mayelyn Alvarez | No corrosion present |
| 06/10/16 | 200 | Mayelyn Alvarez | No corrosion present |
| 06/13/16 | 300 | Mayelyn Alvarez | No corrosion present |
| 06/16/16 | 400 | Mayelyn Alvarez | No corrosion present |
| | | | SAMPLE WAS CLOSED WITH RESULT: Pass |

Viewing Salt Spray Sample: (# 833)

Rod Holder
 Item #: Rod Holder
 Source: G8230
 Date Created: 06/03/16
 Created By: Mayelyn Alvarez
 Start Test
 Time: 6/3/16 8:00
 Test Hours: 400
 Finish Result: **Pass**

Sample Comments:

| Date | Hours | User | Comment |
|----------|-------|-----------------|------------------------------------------------|
| 06/04/16 | 24 | Mayelyn Alvarez | No corrosion present |
| 06/07/16 | 100 | Mayelyn Alvarez | No corrosion present |
| 06/10/16 | 200 | Mayelyn Alvarez | No corrosion present |
| 06/13/16 | 300 | Mayelyn Alvarez | No corrosion present |
| 06/16/16 | 400 | Mayelyn Alvarez | No corrosion present |
| | | | SAMPLE WAS CLOSED WITH RESULT: Pass |

Viewing Salt Spray Sample: (# 834)

Item #: Thru Hull
 Source: G8231
 Date Created: 06/03/16
 Created By: Mayelyn Alvarez
 Start Test
 Time: 6/3/16 8:00
 Test Hours: 400
 Finish Result: Pass

Sample Comments:

| Date | Hours | User | Comment |
|----------|-------|-----------------|--------------------------------------------|
| 06/04/16 | 24 | Mayelyn Alvarez | No corrosion present |
| 06/07/16 | 100 | Mayelyn Alvarez | No corrosion present |
| 06/10/16 | 200 | Mayelyn Alvarez | No corrosion present |
| 06/13/16 | 300 | Mayelyn Alvarez | No corrosion present |
| 06/16/16 | 400 | Mayelyn Alvarez | No corrosion present |
| | | | SAMPLE WAS CLOSED WITH RESULT: Pass |

Viewing Salt Spray Sample: (# 835)

Item #: Hinge Cast
 Source: G8199
 Date Created: 06/03/16
 Created By: Mayelyn Alvarez
 Start Test
 Time: 6/3/16 8:00
 Test Hours: 400
 Finish Result: Pass

Sample Comments:

| Date | Hours | User | Comment |
|----------|-------|-----------------|--------------------------------------------|
| 06/04/16 | 24 | Mayelyn Alvarez | No corrosion present |
| 06/07/16 | 100 | Mayelyn Alvarez | No corrosion present |
| 06/10/16 | 200 | Mayelyn Alvarez | No corrosion present |
| 06/13/16 | 300 | Mayelyn Alvarez | No corrosion present |
| 06/16/16 | 400 | Mayelyn Alvarez | No corrosion present |
| | | | SAMPLE WAS CLOSED WITH RESULT: Pass |

Viewing Salt Spray Sample: (# 836)

Item #: Steering Wheel
 Source: G8231
 Date Created: 06/03/16
 Created By: Mayelyn Alvarez
 Start Test
 Time: 6/3/16 8:00
 Test Hours: 400
 Finish Result: **Pass**

Sample Comments:

| Date | Hours | User | Comment |
|----------|-------|-----------------|------------------------------------------------|
| 06/04/16 | 24 | Mayelyn Alvarez | No corrosion present |
| 06/07/16 | 100 | Mayelyn Alvarez | No corrosion present |
| 06/10/16 | 200 | Mayelyn Alvarez | No corrosion present |
| 06/13/16 | 300 | Mayelyn Alvarez | No corrosion present |
| 06/16/16 | 400 | Mayelyn Alvarez | No corrosion present |
| | | | SAMPLE WAS CLOSED WITH RESULT: Pass |

Before and After Pictures:



















